


Service  
Service  
Service

# Service Manual

For record changer see 22GC051/R version



Safety regulations require that the set be restored to its original condition and that parts which are identical with those specified, be used.

Documentation Technique Service Dokumentation Documentazione di Servizio Huolto-Ohje Manual de Servicio Manual de Servicio



Subject to modification  
4822 726 11776  
Printed in The Netherlands

**PHILIPS**

CS56448

C	701	702,703	713,709	715	706	705	704	708 713 710 707 711 712	718
R	501	502	431		432	504	518	503 505	
MISC	BU1			IC419				428 509-517 429	
								BU2 S403 SK1 D406 D423,424 T408 F1 SK2,3 TS422 TS421 M L426	




Fig. 1

-TS-IC-									
IC419	TBA641B12	4822 209 80271							
TS421	AC187	5322 130 40314							
TS422	BC548B	4822 130 40937							
-D-									
D406	BAX18	5322 130 34121							
D423,424	BY206	4822 130 30839							
-R-									
R428	100 Ω (lin)	4822 100 10075							
R429	2k2 (lin)	4822 100 10029							
R431	220k (log)	4822 105 10287							
R432	100k (spez)	4822 105 10286							
R511	680 Ω - 0.4W ± 2%	5322 116 54534							
R514	1k2 - 0.4W ± 2%	5322 116 54557							
-L-S-									
L426	4 Ω	4822 157 50789							
S403		4822 240 10021							
-SK-									
SK3		4822 272 10083							
-Miscellaneous-									
T408		4822 145 40147							
F1		4822 252 20007							
M		4822 361 20112							

C	712	701	718 702 708÷710 704 707 703	715 713 705 706 711			
R	431 516 509÷512 514 428 429 501 515 513 517	502 503 504	505	432	518	SK3 T408 F1	
MISC	SK1 D423 424	SK 2	L 426 BU1 TS 422 421	BU 2 IC 419	M	D406	





Fig. 2



10699E12

Fig. 3